

RECEIVED

JUL 2 3 2002

Technology Center 2600



🗗 eDrawing Viewer - Pump2.eDw

File View Help





3D Pointer

- 1. ALL BUSSES TO HAVE A 6' DRAFT
- 2. ALL HOLES LABELED "TIC HOLE 6" HAVE A COMPOUND ANGLE
- 3. SEE 100-2032-000 FOR OTHER CASTING DIMENSIONS


## RECEIVED


JUL 2 3 2002





SECTION A-A






How do I create an eDrawing?

Mouse position: 9.16,21.99

AutoCAD 2000 Import CExploring - D\Ne... AutoCAD 2000 - [... Febr





RECEIVED

JUL 2 3 2002

Technology Center 2600

FIG. 4







FIG. 5







How do I create an eDrawing?

Mouse position: 8.73,18.79

BStart ☑ € 🔞 🗷 Ø Ø Ø Microsoft 🛛 Exploring – D\Ne... 🗚 AutoCAD 200 – [ ... 🗗 eDr



7/29 eDrawing Viewer - D: \Opportunities\ForerunnerDemo\Level3\PUMP HOUSINGO.eDw File View Help Shaded D A 50 SECTION A-A RECEIVED JUL 2 3 2002 Technology Center 2600

How do I create an eDrawing?

Mouse position: 0.54,0.55

AutoCAD 2000F... 1 until Land Cap 2000F... 2 until Land Cap 2000F



32






FIG. 8









FG, 10



RECEIVED	<b>₫℃</b>
Technology Center 2699	Untitled 6
	<b>窓口の</b> ISInbox Microsoft QExploring-D\Ne AutoCAD 2004









14/29




FIG. 14

**Technology Center 2600** 





FIG. 15





RECEIVED

JUL 2 3 2002

Technology Center 2600

FIG. 16




FIG. 17






FIG. 18




FIG. 20





FIG. 19





FIG. 21






FIG. 22




FIG. 23






FIG. 24




FIG. 25








FIG. 26

THE STATE OF THE S

24/29





FIG. 27








FIG. 29

27/29






FIG. 30

28/29






FIG. 31




FIG. 32